XMM-Newton and INTEGRAL weekly
Mission Operations Report

XMM-INT-WOPS-23_22-23

Issue 1

Date: 19 June 2023

Marcus Kirsch
OPS-OAX

Distribution List

ESOC	Rolf Densing		Danielle Heinzer
	Dhivya Kishore	Frank Dreger	Andrzej Olchawa
	Andreas Rudolph	xmmintfd@esa.int	Federico Cordero
	XMMINTFCT	Alastair McDonald	Diana Dragostinova
	Marcus Kirsch		Gianluca Gaudenzi
	Jim Martin		
	Marko Butkovic	Martin Unal	
	Stefano Scaglioni		
	EILSservices@esa.int		
		Duncan Warren	
	Richard Southworth	Muhammad Shoaib Malik	
	Jutta Huebner	Elena Garcia Tomas	
	Simon Plum		
ESAC	Carole Mundell	Peter Kretschmar	Matthias Ehle
	Markus Kissler-Patig	Maria Santos Lleo	
	Elsa Montagnon		isocsci@sciops.esa.int
		Pedro Calderon	
		Ricardo Perez	
		Anthony Marston	
ESTEC			Erik Kuulkers
			Guiseppe Sarri
Airbus			
		Tommy Strandberg	
		Susanne Fugger	
Alenia			
	Franco Ravera	Mario Montagna	
Logica			
	COMCS_Helpdesk.de@logicacmg.com		
ISDC			
	Roland Walter		Carlo Ferrigno
NASA			
	DSN.Mission_XMM		
INT-PI			
	Philippe Laurent	J.P. Roques	Giovanni Larosa
	Pietro Ubertini	Wojte Hajdas	Miguel Mas Hesse
	Søren Brandt	Jochen Greiner	
	A. Bazzano		

1. Weekly report

	XMM	Integral
Main activities	- Nominal Operations - Full end to end instrument radiation protection and rejoin - OA OPS tools servers S/W and H/W migration - MCS migration - DABYS D/B prototype - Tolhuin station consolidation - G/S ops automation (part2/ NIS) - Lela final migration to MCS	- Routine science operations - Eclipse season finished
Status and performance of S/C	Nominal for platform and all instruments	Manual transponder swaps following RF switch anomaly
Status and performance of Ground segment	Nominal	Nominal but see anomaly report below
S/C Anomalies	None	- INT_SC-735 IBIS PICSIT PDM08 LATCH UP - INT_SC-732 SPI DPE1 CPU reset
G/S Anomalies	XMM-1532 MUST Database corrupted after Halley Data Center Problem	- INT-3906 Transponder Swap Performed Late - INT-3907 Wrong Command Sent for TRSP Swap - INT-3908 Kiruna Stops Track
Future activities planned	- Manual spacecraft recovery without propellant procedures - CDMU recovery automation - Webserver migration	- Automation of Transponder swap operations - Automation of ground station operations (EVFM) - Disposal optimisation manoeuvre preparation

2. Detailed weekly operational events

note: all times are Zulu (in brackets DOY)

2.1. XMM

- 08/06/2023 (159) 12:52:07: Complete loss of TM from AGO
    - 13:02:07 Requested a different GS. Configuring YTH now
    - 13:02:27 Called FD on-call due to missed/interuppted OSL
    - 13:05:41 SOE on-call informed of situation
    - 13:08:24 YTH is configured. I have requested they move carrier from AGO to YTH.
    - 13:22:34 FD are generating the slew recovery now
    - 14:02:07 Begin PN recovery with X_CRP_EPN_1500
-
- 08/06/2023 (159) 14:06:42: Frames out-of-sync from YTH. Spoke with our RF SOE and we decided to return to AGO. This has been communicated to SSC via ESTRACK
    - 14:06:43 X_CRP_EPN_1500 failed at step #74 due to unstable TM/TC from YTH
    - 15:09:06 X_CRP_EPN_1500 is complete. S/S has been re-enabled

- 10/06/2023 (161) 07:32:19: MCCM: xmca, xlta, xcla1, xcla2, xcla3 red, discrepancy found GMMS: xnisA yellow, Mois grey, FD grey, xgmma blue, gmms opsh1 blue root time 9.6.23 18:24, xgmmb yellow
    - 07:37:34 Speak to Estrack who said there was an airconditioning problem in Halley Server room several servers affected yesterday 9-6-23. They do not have a list of servers that were hit. This might be why xgmma is blue. MOIS is working ok. Cockpit 250011
    - ***See AR XMM-1532 MUST Database corrupted after Halley Data Center Problem***

2.2. INTEGRAL

30/05/2023 (150)
-

31/05/2023 (151)
06:17:17   TPF update failed for SlewID #2640008. FD go ahead for slew without update
08:08:02   OCR#2364 RCS: OPEN LV-A
08:27:00   OCR#2365 RCS: Thermal test T1033 TSW STA PROPB is now CLOSE.
14:53:04   OCR#2366: AOCS reconfig after the last eclipse of the season

01/06/2023 (152)
-

02/06/2023 (153)

-

03/06/2023 (154)

-

04/06/2023 (155)

03:22:03	Complete loss of TM, AR INT-3906
03:41:53	Transponder swop blind.
04:15:23	Slews #26470049, 26470050 and 26470051 missed from timeline.
05:04:41	Manual slew 2647_0501_M.OSL from PID #264700048 to #264700050
05:33:58	Manual slew 2647_0502_M.OSL from PID #264700050 to #264700052
06:18:55	Manual slew 2647_0503_M.OSL from PID #264700052 to #264700053
06:48:17	FDS: TPF 2647_0504_A.0504 applied on A/S to update slew 264700054
16:49:17	SPI DPE crash, AR INT_SC-732, CRP_SPI1_3090 (SPI DPE1 RESET).

05/06/2023 (156)

09:38:47	SPI in PHOTON -> end of SPI DPE reset recovery
10:35:03	OI#2368 Characterisation of Tank Heaters

06/06/2023 (157)

15:58:44	TPF update failed for Slew #26480047 FDS: Failed to determine attitude
16:06:29	FDS: TPF 2648_0500_A.OSL applied on A/S to update slew 264800047
17:42:39	OSL #26480050 failed, TC A3086 "SUN STEERING INI" Failed release PTV
17:55:00	Manual slew 2648_0501_M.OSL from PID #264800049 to #264800050
18:10:36	FDS: TPF 2648_0502_A.OSL applied on A/S to update slew 264800051

07/06/2023 (158)

02:44:32	OOL AD5230H: "OTF Toggle Alert". PID 26480066. OEMs: "YAW ERROR".
02:47:00	FDS: TPF update failed for SlewID #26480067. Guidestar lost after slew.
02:47:09	FDS: TPF 2648_0503_A.OSL applied on A/S to update slew 26480067.

08/06/2023 (159)

01:45:01	TRSP Swaps. TX2 --> TX1. Test TCs not reaching SC. CORTEX2 TC binds but in "configured" state. Estrack re-run TRSP swap job. Test Cmd OK. No impact.

09/06/2023 (160)

-

10/06/2023 (161)

-

11/06/2023 (162)

16:00:58   IBIS PICSIT PDM08 LATCH UP. IBIS to STDBY, reset PDM08. FCP_IBIS1_0313 / 0329. AR INT_SC-735

17:27:11   Problems acquiring TM on either chain.

17:44:56   Blind Transponder swop executed.

17:51:25   Slew #26500029 failed

18:03:22   Manual slew 2560_0500_M.CSL. Some commands failed during uplink.

18:39:28   Manual slew 2560_0501_M.OSL from PID #26500029 to #26500031

19:05:03   FDS: TPF 2650_0502_A.OSL applied on A/S to update slew 26500032

12/06/2023 (163)

-